

Cladding and Screening Maintenance Guidelines

Unpigmented Sioo:x Products

SiOO:X finish

Light surface mould, dirt or discolouration.

Brush surface of dry timber gently with dry soft bristle brush.

Application of **SiOO:x Surface Protection Panel (Step 2)** may be necessary if Surface Protection is removed

Optionally apply slow acting neutral pH mouldicide to dry timber.



Clean every 12 months minimum or when needed with **SiOO:x Maintenance Wash**. Apply with soft brush, rinse with water.

Check and remediate cladding system as necessary to maintain weather-tightness.

After approximately 4 to 7 years: Clean with **SiOO:x Maintenance Wash** and apply one coat of **SiOO:x Surface Protection Panel (Step 2)** to dry timber.

After approximately up to 12 years: Clean with **SiOO:x Prewash** then apply full treatment – two coats **SiOO:x Wood Protection Panel (Step 1)** + one coat **SiOO:x Surface Protection Panel (Step 2)** to clean, dry timber.

MORE INFO HERE: sioox.com/en/how-to-do-it/
Re-coat intervals are a indicative only and will depend on climatic conditions, construction and wood species.

Repairing damage
For minor surface damage apply **SiOO:x Surface Protection Panel (Step 2)**.

Where raw timber has been exposed apply full treatment; **SiOO:x Wood Protection (Step 1)** + **SiOO:x Surface Protection (Step 2)** to the exposed areas ensuring clean, dry timber.

Heavy persistent mould, dirt, or stubborn stains.

Clean with **SiOO:x Prewash** and a soft brush, rinse with water. Wait until wood is dry and then apply one coat of **SiOO:x Surface Protection Panel (Step 2)** to dry timber.

Optionally apply slow acting neutral pH mouldicide to dry timber.

